

MAJOR POINTS OF EXTENSION

The numbering refers to sections and subsections of the new version of the paper.

ABSTRACT

The abstract has been modified.

1. INTRODUCTION

A comprehensive bibliographic analysis (Masonry churches diagnostics, Analytic Hierarchy Process, Decision Support System) has been included.

2. AHP APPLICATION

2.1. Step 1: the problem of the masonry damages and quality

The third macro-criterion has been added to take the state of conservation of Wood Floor into account (improved version of Figure 2).

MASONRY BUILDING PERFORMANCES




Fig.2. Structure of the Problem: Masonry diagnostics

2.2. Step 2: weight evaluation

The example of the Tie Rods (Figure 3) study has been showed to better explain the qualitative analysis to achieve the judgment matrix and extract the tabulated weights.

Tie Rods evolution over time		
Before 1500 A.D.	-Wood Tie-rods; -Strong aesthetic impact; -High weight; -Problems related to the degradation both of wood and steel; -Locking bolt.	
Between 1500 and 1700 A.D.	-Steel Tie-rods; -Locking bolt; -Clamping techniques not very effective.	
Between 1800 and 1900 A.D.	-Advanced clamping systems; -Static or aesthetic needs; -Stiffening ribs; -Multiple threaded and tensioned rods; -Square-headed or round-headed bolt.	
	-Bilateral connection on the wooden beams; -Bolted systems.	
After 1900 A.D.	-Advanced clamping systems; -Static or aesthetic needs; -Corrosion protection by austenitic or duplex steels; -Polymeric sheath inside between steel and masonry to avoid direct contact; -Remaining voids filled by injection of resins; -Chain joining via sleeve for threaded junction, clamped, clamped, bolted or grooved; -Bars equipped with threaded ends for clamping;	

Fig. 3. Study of the Tie Rods evolution over time.

3. INTEGRATION OF THE AHP-BASED APPROACH IN A DSS

A novel section has been developed to explain the integration of the AHP-based approach in a DSS (including novel Figure 4 and Figure 6)




Figure 4. Components of the DSS Architecture.





Figure 6. Components of the DSS Architecture.

4. CASE STUDY

The text has been modified and enriched with more representative images (Figure 7a,b; Figure 8a,b; Figure 9)



a)



b)

Figure 1. "SS. Salvatore's" church: a) principal façade; b) church's plan

LOCATION DATA Italy Puglia Capurso (BA) Via Carone n.2			
IDENTIFICATION DATA SS. Salvatore's Church 1541 Late Romanesque Basilical plan Three naves			
	MACROELEMENT CHAMBER	10,00	
	ELEMENT PILLAR	8,65	
	MQI NC PC C PARAMETERS	1	
	(Masonry Quality Index)	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Resistance of the elements	1
		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Horizontal Rows	2
		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Presence of diatones	1
		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Shape of the resistant elements	3
		<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Off vertical joints	0
		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Dimension of the resistant elements	1
	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Mortar quality	2	
CRACKS YES NO TYPOLGY AND MAGNITUDE	10,00		
<input checked="" type="checkbox"/> <input type="checkbox"/> VERTICAL C			
MANIFESTATION YES NO TYPOLGY	10,00		
<input checked="" type="checkbox"/> <input type="checkbox"/> DEFORMATION			
I_M		8,75	

a)

LOCATION DATA Italy Puglia Capurso (BA) Via Carone n.2		
IDENTIFICATION DATA SS. Salvatore's Church 1541 Late Romanesque Basilical plan Three naves		
	CONNECTIONS	
	ANCHOR SYSTEM YES NO TYPOLGY	
	<input type="checkbox"/> <input type="checkbox"/> locking bolt and wood rod	9,59
	STEEL CORROSION	
	MEDIUM	
FLOOR/WALL YES NO JOINT	6,67	
<input type="checkbox"/> <input type="checkbox"/> INTERLOCKING LEANING JOINT		
WALL/WALL YES NO DISCONNECTION/VERTICAL CRACK C	0,00	
<input type="checkbox"/> <input type="checkbox"/>		
I_C		7,64
ELEMENT TIMBER TRUSS		10,00
BIOLOGICAL CRITICALITY YES NO MOISTURE		
<input type="checkbox"/> <input type="checkbox"/> SURFACE ALTERATION	HOLES	4,31
EXTENSION	50%	
MECHANIC CRITICALITY YES NO CRACKS		0,00
<input type="checkbox"/> <input type="checkbox"/> DEFORMATIONS		
CLASSIFICATION (UNI 11219:2004)		
SIZE OF KNOTS	I II III	10,00
<input type="checkbox"/> 20% <input type="checkbox"/> 30% <input type="checkbox"/> 50%		
SHRINKAGE CRACKS	S W P	8,00
<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
I_W		

b)

Figure 2. Survey forms: a) damaged Pillar; b) damaged connection system.




Figure 3. Technical drawing by specialists with damages representation

5. CONCLUSION

Novel conclusions have been added.

REFERENCES

30 references have been added.